
Hotkeys

ALT + P	Change page (same as the <u>D</u> isplay, <u>O</u> pen menu item, keys ALT-D, O).
ALT + Q	Exit TPS (same as the <u>F</u> ile, <u>E</u> xit menu item, keys ALT-F,X).
CTRL F	Freeze display (no menu equivalent).
CTRL R	Reset statistics (no menu equivalent).
CTRL P	Print display (same as the <u>F</u> ile, <u>P</u> rint menu item, keys ALT-F, P).
ESC	Toggle step mode, same as <u>O</u> ptions, <u>S</u> witches, <u>S</u> tep mode menu item, keys ALT-O, S, S.
DEL	Refresh all plots (clear the plot trace).
SHIFT DEL	Refresh the entire screen.
'+'	Speed up TPS, i.e. halve the loop-time.
'-'	Slow down TPS, i.e. double the loop-time.
PGUP	Turn to the next page.
PGDN	Turn to the previous page.